

2019 Wildwood Townhomes Association Tree Inventory

Tree	Species	Size	Likelihood of Failure- Class A	Likelihood of Target Impact- Class B	Consequences of Failure- Class C	Subtotal 1 (A+B+C)	Target- Class D	Species- Class E	Action- Class F	Subtotal 2 (D+E+F)	Prioritized Rating (Subtotal 1 X Subtotal 2)	Notes
1	Narrowleaf Cottonwood	38	4	4	4	12	4	4	4	12	144	Tree is dead, removal of tree is recommended
2	Narrowleaf Cottonwood	29.5	1	2	2	5	4	4	1	9	45	Overpruning of live branches has resulted in multiple stems of epicormic branching
3	Narrowleaf Cottonwood	24.7	1	2	2	5	4	4	1	9	45	Overpruning of live branches has resulted in multiple stems of epicormic branching
4	Narrowleaf Cottonwood	25.2	1	2	2	5	4	4	1	9	45	Overpruning of live branches has resulted in multiple stems of epicormic branching
5	Narrowleaf Cottonwood	30	2	2	2	6	3	4	3	10	60	Prune dead wood
6	Narrowleaf Cottonwood	35	2	2	2	6	3	4	3	10	60	Prune dead wood/ Cavities are present
7	TREE HAS BEEN REMOVED	-	-	-	-	-	-	-	-	-	-	TREE HAS BEEN REMOVED
8	Narrowleaf Cottonwood	16	2	2	2	6	2	4	3	9	54	Prune dead wood/ Previously failed limb
9	Narrowleaf Cottonwood	19.5	2	3	2	7	1	4	1	6	42	
10	Narrowleaf Cottonwood	25.3	2	2	2	6	2	4	3	9	54	Prune dead wood
11	Narrowleaf Cottonwood	29	2	3	3	8	3	4	2	9	72	Tree lacks vigor/ Co-dominant stem at 25 feet
12	Narrowleaf Cottonwood	32.2	2	3	3	8	3	4	3	10	80	Prune dead wood/ Co-dominant stem at 30 feet/ Cavity is present
13	Narrowleaf Cottonwood	32.5	3	3	2	8	2	4	3	9	72	Prune dead wood/ No tag present
14	Narrowleaf Cottonwood	31.5	2	3	3	8	3	4	2	9	72	
15	Narrowleaf Cottonwood	26.6	1	2	1	4	1	4	1	6	24	Co-dominant trunk
16	Narrowleaf Cottonwood	22.2	3	1	1	5	1	4	1	6	30	
17	Narrowleaf Cottonwood	30.5	2	2	3	7	3	4	2	9	63	Co-dominant stem has been removed
18	TREE HAS BEEN REMOVED	-	-	-	-	-	-	-	-	-	-	TREE HAS BEEN REMOVED
19	Narrowleaf Cottonwood	20.8	1	1	1	3	1	4	1	6	18	Co-dominant stem
20	Narrowleaf Cottonwood	22.3	2	2	1	5	1	4	1	6	30	Prune dead wood, co-dominant stem
21	Narrowleaf Cottonwood	22	1	2	1	4	2	4	1	7	28	Prune dead wood/ Tree has been previously topped/ Cavity present/ Decay probable
22	Narrowleaf Cottonwood	20.4	2	1	1	4	1	4	1	6	24	Prune dead wood/ Co-dominant stem
23	Narrowleaf Cottonwood	25.8	1	1	1	3	1	4	1	6	18	Previously topped tree, existing crown is made up of epicormic branches/ Large cavity makes an excellent wildlife tree
24	Narrowleaf Cottonwood	42.2	2	2	3	7	3	4	1	8	56	Decay present at base of tree
25	Narrowleaf Cottonwood	26.3	2	3	3	8	3	4	1	8	64	Previously topped tree/ Cavity present at top
26	Narrowleaf Cottonwood	24.8	3	3	3	9	3	4	3	10	90	Prune dead wood/ Previously topped tree/ Poor pruning cuts not flush with tree collar
27	Narrowleaf Cottonwood	25.5	2	3	2	7	3	4	3	10	70	Prune dead wood/ Dead wood over road
28	Narrowleaf Cottonwood	20	1	1	1	3	3	4	1	8	24	Co-dominant stem/ Evidence of aphids
29	Narrowleaf Cottonwood	16.8	1	2	1	4	1	4	1	6	24	
30	Narrowleaf Cottonwood	18.3	2	1	1	4	1	4	1	6	24	Co-dominant stems at 2 feet
31	Narrowleaf Cottonwood	18	1	2	1	4	1	4	1	6	24	At house corner
32	Narrowleaf Cottonwood	17.3	2	2	1	5	2	4	2	8	40	Prune dead wood
33	Narrowleaf Cottonwood	18.1	2	2	1	5	3	4	3	10	50	Prune dead wood
34	Narrowleaf Cottonwood	23.3	2	3	2	7	3	4	4	11	77	Prune dead wood
35	Narrowleaf Cottonwood	17	1	1	3	5	3	4	1	8	40	
36	TREE HAS BEEN REMOVED	-	-	-	-	-	-	-	-	-	-	TREE HAS BEEN REMOVED
37	Narrowleaf Cottonwood	18.3	2	3	1	6	3	4	1	8	48	
38	Narrowleaf Cottonwood	18.2	2	3	1	6	3	4	1	8	48	Tree leaning over structure
39	Narrowleaf Cottonwood	17	1	1	1	3	3	4	1	8	24	No tag/ Very little dead wood
40	Narrowleaf Cottonwood	17.7	1	1	1	3	3	4	1	8	24	Very little dead wood

2019 Wildwood Townhomes Association Tree Inventory

Tree	Species	Size	Likelihood of Failure- Class A	Likelihood of Target Impact- Class B	Consequences of Failure- Class C	Subtotal 1 (A+B+C)	Target- Class D	Species- Class E	Action- Class F	Subtotal 2 (D+E+F)	Prioritized Rating (Subtotal 1 X Subtotal 2)	Notes
41	Narrowleaf Cottonwood	13.2	1	1	1	3	3	4	1	8	24	Very little dead wood
42	Narrowleaf Cottonwood	19.2	2	3	2	7	3	4	1	8	56	Previously topped tree/ Cavity present
43	Narrowleaf Cottonwood	30.3	2	3	2	7	3	4	1	8	56	Co-dominant at 2 feet/ Previously topped tree/ Cavity present
44	Narrowleaf Cottonwood	21.5	1	1	2	4	2	4	1	7	28	Previously topped tree/ Tree up against fence, bark wound exists against fence
45	Narrowleaf Cottonwood	23	2	2	2	6	1	4	1	6	36	Previously topped tree
46	Narrowleaf Cottonwood	23.2	2	2	1	5	3	4	1	8	40	Previously topped tree
47	Narrowleaf Cottonwood	14.7	2	2	1	5	3	4	1	8	40	Prune dead wood/ Injury on west side of trunk
48	Narrowleaf Cottonwood	20	1	2	2	5	2	4	1	7	35	Tree leaning over canal
49	Narrowleaf Cottonwood	19	1	2	1	4	3	4	1	8	32	Previously topped/ Heavy epicormic branching
50	Narrowleaf Cottonwood	21	2	2	3	7	3	4	1	8	56	Previously topped/ Heavy epicormic branching/ Cavity present
51	Narrowleaf Cottonwood	20.8	2	2	3	7	3	4	1	8	56	Previously topped/ Heavy epicormic branching
52	Narrowleaf Cottonwood	16.9	1	1	1	3	2	4	1	7	21	
53	Narrowleaf Cottonwood	19	1	1	1	3	2	4	1	7	21	No tag
54	Narrowleaf Cottonwood	20	1	1	1	3	2	4	1	7	21	Previously topped
55	Narrowleaf Cottonwood	20.5	1	1	1	3	3	4	1	8	24	Previously topped
56	Narrowleaf Cottonwood	20	2	3	3	8	3	4	1	8	64	No tag
57	Narrowleaf Cottonwood	17	2	2	2	6	3	4	1	8	48	
58	Narrowleaf Cottonwood	18	2	3	2	7	3	4	1	8	56	Injury on West Side of Trunk
59	Narrowleaf Cottonwood	19.6	2	2	2	6	3	4	1	8	48	
60	Narrowleaf Cottonwood	26.5	1	2	2	5	1	4	1	6	30	
61	TREE HAS BEEN REMOVED	-	-	-	-	-	-	-	-	-	-	TREE HAS BEEN REMOVED
62	Narrowleaf Cottonwood	14	1	1	1	3	1	4	1	6	18	Co-dominant at 3 feet
63	Narrowleaf Cottonwood	24.9	1	1	3	5	3	4	1	8	40	
64	Narrowleaf Cottonwood	25.7	2	2	1	5	3	4	1	8	40	
65	Narrowleaf Cottonwood	20.8	2	2	1	5	3	4	1	8	40	
66	TREE HAS BEEN REMOVED	-	-	-	-	-	-	-	-	-	-	TREE HAS BEEN REMOVED
67	TREE HAS BEEN REMOVED	-	-	-	-	-	-	-	-	-	-	TREE HAS BEEN REMOVED
68	Narrowleaf Cottonwood	21.5	1	1	1	3	4	4	1	9	27	Previously topped
69	Narrowleaf Cottonwood	15.7	2	2	2	6	4	4	1	9	54	Cavity present
70	Narrowleaf Cottonwood	25	1	2	2	5	4	4	1	9	45	Previously topped
71	Narrowleaf Cottonwood	17.7	1	1	1	3	4	4	1	9	27	Previously topped
72	Narrowleaf Cottonwood	18.2	2	2	2	6	4	4	1	9	54	Small deadwood
73	TREE HAS BEEN REMOVED	-	-	-	-	-	-	-	-	-	-	TREE HAS BEEN REMOVED
74	Narrowleaf Cottonwood	31.6	1	1	1	3	4	4	1	9	27	Tree has been previously topped/ Decay probable
75	Narrowleaf Cottonwood	30.9	2	2	2	6	4	4	3	11	66	Prune dead wood/ Tree has been previously topped
76	Blue Spruce	26.8	1	2	3	6	3	3	1	7	42	Shallow roots/ Vulnerable to whole tree failure when ground is saturated
77	Englemann Spruce	21.4	1	2	3	6	3	3	1	7	42	Shallow roots/ Vulnerable to whole tree failure when ground is saturated
78	Willow spp.	23.5	1	2	2	5	3	4	1	8	40	